

FIG. 1

FIG. 1 is a perspective view of a mechanical assembly. A large cylindrical component (1) is connected via a shaft (20) to a series of rollers (3, 4, 5, 6, 7). A belt (2) is looped around rollers 23, 24, 25, and 51. A curved component (8) is positioned at the end, with a small rectangular part (99) on its surface. Arrows II and III indicate directions of movement or force.

FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9





FIG. 10






FIG. 12




FIG. 13




FIG. 14

FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20

